


ROOF REPORT

Order #: 1234



Project Location:


123 Main Street, Apt 4B, Anytown, NY 10001

Total Area: 3326.64 sqft
Number of facets: 15
Primary slope/pitch: 6/12

This report is provided by **XMATE Sketch Lab™** under a limited, non-transferable license for a single project use. All sketches, diagrams, and related content remain the exclusive intellectual property of **XMATE Sketch Lab™**. Any reproduction, distribution, or use beyond the agreed purpose without prior written authorization is strictly prohibited. Unauthorized use may result in legal action. © 2025 **XMATE Sketch Lab™**. All rights reserved.




DIAGRAM





LENGTH MEASUREMENT REPORT




EAVE	199.67 ft
FLASH	6.67 ft
HIPS	138.44 ft
PERIMETER	263.30 ft
RIDGES	44.33 ft
RAKES	63.63 ft
STEP FLASHING	5.87 ft
VALLEYS	64.69 ft



AREA MEASUREMENT

123 Main Street, Apt 4B, Anytown, NY 10001




FACE	SQ FT	SLOPE/PITCH
F1	947.73	6
F2	104.60	6
F4	674.22	6
F5	334.46	6
F6	468.05	6
F8	245.25	6
F9	437.95	6
F11	82.21	6
F14	11.99	6
F15	4.04	6
F17	4.04	6
F19	4.04	6
F21	4.04	6
F23	4.04	6

ESTIMATED TOTAL 3326.64




SLOPE/PITCH MEASUREMENT





SUMMARY REPORT



MEASUREMENTS	
TOTAL ROOF AREA	3326.64 sqft
TOTAL SLOPE AREA	3326.64 sqft
TOTAL ROOF FACETS	15
PRIMARY SLOPE/PITCH	6/12
TOTAL EAVES	199.67 ft
TOTAL FLASH	6.67 ft
TOTAL HIPS	138.44 ft
PERIMETER	263.30 ft
TOTAL RIDGES	44.33 ft
TOTAL RAKES	63.63 ft
TOTAL STEP FLASHING	5.87 ft
TOTAL VALLEYS	64.69 ft
HIP + RIDGES	182.77 ft
EAVES + RAKES	263.3

Slope/Pitch	6/12
Area (sqft)	3326.64
Squares	33.27



LEGAL NOTICE AND DISCLAIMER

123 Main Street, Apt 4B, Anytown, NY 10001

The materials in this report are provided by **XMATE Sketch Lab™** "as is," without warranties of any kind, express or implied. While prepared with care, no guarantee is made regarding content accuracy, completeness, or suitability for any particular purpose.

All diagrams and measurements are intended for reference only. Contractors and adjusters are responsible for performing an on-site inspection to verify conditions before using this report for construction, repair, or claims.

In the event of an error, the sole remedy available is a refund of the fees paid to obtain this report. **XMATE Sketch Lab™** shall not be liable for any indirect, incidental, or consequential damages arising from the use of this report.